

Attachment A

Photos of Sydney Town Hall Roof Elements

Attachment A – Reference Photos of Sydney Town Hall Roof



Figure 1. South-western turret (foreground) and South-eastern turret (background).



Figure 2. Deterioration to turret.



Figure 3. Northern Dome.



Figure 4. Southern Dome.



Figure 5. Interior of Dome showing line of rusted steel on L-angle base plate probably caused by water ingress.



Figure 6. Dome cupola cladding showing the loss of galvanising and associated corrosion.



Figure 7. Dome Lantern, showing the deteriorated condition of the original galvanized steel sheet.



Figure 8. Dome Lantern, interior face of a portion of the removed original architrave panels with visible corrosion.