

Attachment A

Location Plan and Site Photos

Cooper Street and Adelaide Street Reserves, Surry Hills





Upper Cooper - Looking west towards Cooper St from Riley St. Layout of pathways & barriers confusing for users. Cyclists have created an unsafe desire line through the planting. A small “low value” tree is in the centre of the unused plaza with no seating. End of life lighting visible amongst the many mature shade trees. The retaining walls are damaged due to tree roots.



Upper Cooper - Looking east towards Riley Street from Cooper Street. The balustrade and walls act as visual and physical barrier. Planting is looking tired. Mature trees flank the reserve. Steep level change across the site visible.



Lower Cooper – Looking north to Cooper Street. The turf is heavily worn out under the canopy of both the existing mature trees. Paths are in a good condition with some tree root lifted paving around the Plane tree. One bollard is dislodged. Existing benches are in good condition. Lighting is at end of life.



Lower Cooper - Looking southwest. The turf is worn out on the corners due to pedestrian movements. Footpath along Cooper Street is narrow and obstructed by the turf. Lots of vertical fixtures cluttering this view.



Adelaide Street Reserve – looking southwest towards Adelaide Street from Little Riley Street. Turf is in poor condition due to pedestrian traffic and shade from mature existing trees. Paths are in a good condition with some tree root lifted paving around Eucalyptus tree. End of life lighting and signage is visible.



Adelaide Street Reserve – looking northeast towards Little Riley Street from Adelaide Street. Some blank spaces in planter beds. Retaining wall and paths are in a good condition with some pavers lifted. Shade from mature existing trees.