

ATTACHMENT A

ATTACHMENT A

PHOTOGRAPHS OF THE BRIDGE

ATTACHMENT A

ATTACHMENT A – PHOTOGRAPHS OF THE BRIDGE



View of bridge from Sir John Young Crescent



Bridge deck with areas of rust to be treated and deck repainted

ATTACHMENT A



Fence to be removed, repainted and reinstalled



Fence support angles to be replaced

ATTACHMENT A



Mast and steel support tendons to be cleaned and repainted



Concrete abutment and lawn to be rebuilt

ATTACHMENT A



Bridge joint sealant to be removed and replaced



Underside of bridge to be cleaned and repainted