

Local Planning Panel

14 December 2022

Application details

Address: 169-173 Victoria Street and 92-98 Brougham Street, Potts Point

Application Number: D/2022/927

Applicant: PG Capital Pty Ltd

Owner: Harrphil Pty Limited and the Owners - Strata Plan No 17354

Architect: Woods Bagot

Planning Consultant: Ethos Urban

Heritage Consultant: Urbis

Proposal

- adaptive reuse of the Piccadilly Hotel and terrace buildings fronting Victoria Street and Brougham Street
- including demolition, alterations and additions, tree removal and landscaping
- to provide hotel accommodation and food and drink premises uses

Recommendation

deferred commencement - subject to conditions

Notification

- exhibition period 23 August 2021 to 21 September 2021
- 1,381 owners and occupiers notified
- 18 submissions received
- 1 support, 1 owner's comment and 16 objections

Submissions

- visual and acoustic privacy
- structural impacts
- safety and security
- noise and dust
- traffic and parking
- public domain improvements
- street tree protection and tree retention
- site access


- acoustic report accuracy
- overdevelopment
- unclear plant provision
- dilapidation reports
- tower crane encroachment
- accessible amenities
- anti-social behaviour
- view sharing and view loss

Submissions



N

subject site




Site











former Golden Apple building - Victoria Street



10



south of site north of site

Victoria Street






92 and 94 96 and 98



looking north along Brougham Street





north south










rear of site - Hourigan Lane

Proposal




demolition plans - elevations




demolition plans - sections

demolition plans - sections





lower ground floor plan











Brougham Street level 2 floor plan





level 1 floor plan






level 2 floor plan



level 2 mezzanine plan












east and west elevations




east-west section and south elevation




north-south section and north elevation





roof and facade details



SUM PROPUR METAL WHOOM PRIMING - CHARGOS.

materials and finishes

MART PRODUCTION OF THE PRODUCT OF TH


GALVANIERO CORPLIGATED STEEL NOOF SHEETING





Photomontage – Victoria Street



Photomontage – Brougham Street







existing proposed

Photomontage – aerial

Compliance with key LEP standards

	control	proposed	compliance
height	12m	14.99m	no clause 4.6 variation request supported
floor space ratio	1.7:1	1.93:1	no clause 4.6 variation request supported

Compliance with DCP controls

	control	proposed	compliance
height in storeys	4 storeys (Victoria St)	4 storeys	yes
	2 storeys (Brougham St)	3 storeys to rear of terraces	no 3 storeys supported
street frontage height	2 storeys (Brougham St)	2 storeys	yes

Compliance with DCP controls


	control	Proposed	compliance
floor to floor heights	4.5m ground floor level	existing floor levels retained	no, but acceptable
	3.6m upper floor levels		
deep soil	10-15% (131-197m ²)	9.4% (124m²)	no, but acceptable
bicycle parking	28 spaces	15 spaces	no, condition proposed to require compliance

Hours of operation


	base hours & extended hours	proposed hours	recommended hours
hotel accommodation hours	24 hours	24 hours	24 hours
indicative food and drink premises	extended hours until midnight	subject to future applications	subject to future applications

Issues

- height
- floor space ratio
- heritage
- view sharing
- storey height
- future use and operation




- non-compliance with height results from new roof additions
- majority of development under height limit



- no significant environmental impacts arising from non compliance
- clause 4.6 variation request supported

Floor Space Ratio



 non-compliance with floor space ratio results from adaptive reuse of existing buildings, conversion of basement space and partial enclosure of garden area



- no significant environmental impacts arising from non compliance
- clause 4.6 variation request supported


Heritage



conservation works to Piccadilly Hotel building facade



Current image of the west facing Piccadilly facade, showing signage, bricked in windows and roof plant




STING



Filled in windows reopened with original focade on replaced with a covered openings restored, and signage repaired



Soho club extension removed and replaced with modern loggia



Key

- Remove flues and AC units from the roof, with new diagrid roof housing restaurant and concealing plant.
- Signage repainted and restored
- Rear facade repaired, with pipe and add one removed and bricks replaced
- 4. Soho club addition removed and replaced
- Original windows reopened where they have been bricked up over time
- 6. Connections to Brougham Street terraces added
- 7. Ground level expavated

169 Victoria Street

Victoria Street Facade

- 1. Original Victorian detailing restored and celebrated
- 2. Second floor windows replaced, with view anto Victoria Street reinstated
- 3. Exterior walls repainted in a light cream and eau de nil
- 4. Original ironwork stripped back and repainted
- 5. Any non-original doors and windows to be replaced to match original proportions, with access to the balcony from the interior restored
- 6. Facade cleared of later works, including plumbing and electrical wiring

19th Century The Grand Townhouse

- The original building was a simple wellproportioned sandstone terrace, with two rooms per floor and a generous.
- Photo opposite is from 1930 - some balcony space has already been



Early 20th Century Multi Unit Occupancy

- From the 1940s to the 1960s the rest of the balconies are claimed as internal spaces, with structure built out to the street boundary
- Bathrooms and kitchens likely installed in the filled in balconies



Late 20th Century The Brothel

- In 1980, alterations were made to the terrace, reinstating the balconies and splitting the terrace into four units
- The terrace was developed into the Golden Apple brothel in 1985. with additions added to thereor
















Preserved Victorian detailed to be restored and celebrated

PROPOSED

Hourlaan Lane Facade

- 1. Facade cleared of non original elements, with extensions replaced with new metal and
- 2. Existing exterior wall repainted in a light cream and eau de nile
- 3. West elevation re-wilded, with planting added to new insertion and to western terrace on the ground floor
- 4. Garage door removed
- 5. Staff bicycle parking installed







1980s additions removed

conservation works to former Golden Apple building



Image of 96 Brougham Street, showing the 1930s brick renovation which will be removed






Later dormer additions removed; with smaller, more traditional dormers installed



Original detailing restored and repainted

- 1. Party walls reinstated. Ensure flashings and details match heritage dimensions
- Large dormers removed to be replaced with smaller DCP. compliant dormers. Dormers to be pushed further back
- 3. 1935/36 brick alteration to be removed from 96, with the terrace to be restored to its original height and proportions
- 4. Ridge height to be raised by 440-530mm to create usable
- space. Also includes ridge height reduction by 890mm to 96 Roof cladding replaced
- 6. Crude 98 balcony demolished and restored to original
- 7. Front brick walls removed and replaced with picket fencing
- B. Remaining original details restored, including ironwork and door frames
- 9. Ground floor windows to be maintained IDA showed proposed extension to create doors)
- 10. Exterior walls repainted
- 11. Gardens to be uniquely and individually planted with native flora, reinforcing the separate character of each terrace
- 12. Additional detail to match existing to gable ends




new roof over Piccadilly Hotel supported:

- no significant impacts on heritage building fabric
- no unacceptable visual impacts to appearance of heritage item from the public domain

Views



no significant view impacts from submitter's property







North Elevation of 181-183 Victoria Street













Unit 4 - Window 1

Unit 4 - Window 1 - rotated to show iconic view

comparative view study images demonstrate retention of iconic views from sunroom

• comparative view study images demonstrate retention of iconic views from lounge

View Analysis - 181-183 Victoria Street
















Height in storeys



non-compliance with two storey height control supported:

- terrace row to be restored
- terrace row presents as two storeys to street
- form of additions does not result in significant impacts

Future Use and Operation

- indicative food and drink premises proposed
- conditions recommended to require a separate application or applications for detailed fit out and use, including patron capacity and hours of operation

Recommendation

deferred commencement consent - subject to conditions including requirements for:

- structural design and details
- public art
- fire hydrant design modification and details
- rooftop photovoltaic system design modification and details