
Attachment C

Inspection Report
11 Ward Avenue, Potts Point



Council investigation officer Inspection and Recommendation Report Clause 17(2), Part 8 of Schedule 5, of the Environmental Planning and Assessment Act 1979 (the Act)

File: CSM 3052802 Officer: D McLennan Date: 27 October 2023

Premises: 11 Ward Avenue, Potts Point

Executive Summary:

Council received correspondence from the Commissioner of Fire and Rescue NSW (FRNSW) in relation to the subject premises on 18 September 2023 with respect to matters of fire safety.

The premises consists of a five-level building with the following approved uses: basement bathroom facilities and plant rooms, ground floor retail and residential apartments and the remaining levels residential apartments.

An inspection of the premises undertaken by a Council investigation officer in the presence of the building manager revealed the premises are deficient in fire safety and egress provisions in the following areas:

- (i) Inadequate fire detection and alarm systems;
- (ii) A lack of adequate facilities for firefighting;
- (iii) Suitable fire resisting construction to prevent the spread of fire;
- (iv) Safe emergency egress for occupants to safety evacuate the building in the event of a fire.

Council investigations have revealed that the premises are deficient in the provisions for fire safety and that a fire safety order is to be issued under Schedule 5 of the Environmental Planning and Assessment Act, 1979 so as to ensure and promote adequate facilities for fire safety/fire safety awareness.

Observation of the external features of the building did not identify the existence of any combustible composite cladding on the façade of the building.

Chronology:

Date	Event			
15/09/2023	FRNSW correspondence received regarding premises 'Mixed use residential flat			
	building' 11 Ward Avenue Potts Point.			
10/10/2023	An inspection of the residential part of the subject premises was undertaken by a			
	Council officer, in the presence of the building manager, revealed:			
	A current Annual Fire Safety Statement displayed prominently in an unlocked			
	glass notice board of the residential ground floor foyer.			
	The Fire Detection and Controlling Indicating Equipment (FDCIE) displayed			
	faults and isolations.			
	Lack of suitable exit and directional exit signage			
	 Lack of a suitable second exit servicing the residential part of the premises. 			
	The service tags of portable fire extinguishers and fire hose reels were last			
	tagged in August 2023			
	Sounders for the Building Occupant Warning System located at irregular			
	intervals.			

Date	Event		
25/10/2023	A follow up inspection of the commercial areas and common areas of the entire premises undertaken by a Council officer, in the presence of the building manage revealed:		
	 The Fire Detection and Controlling Indicating Equipment (FDCIE) did not display faults and isolations. Lack of fire separation in the basement. 		
	 Part of the basement associated with the residential part of the building was vacant. 		
	 Electrical meter boards and equipment without non-combustible covers and smoke seals located within the only available exit in the basement. 		
	 A smoke detector located in a commercial tenancy that was suspended from, instead of being directly fixed, to the ceiling. 		
30/10/2023	A Notice of Intention to give a Fire Safety Order was issued to the owners of premises.		

FIRE AND RESCUE NSW REPORT:

References: BFS21/3944 (17829); 2023/541889

Fire and Rescue NSW conducted an inspection of the subject premises on 15 August 2023 after receiving an enquiry on 19 October 2021 regarding the delayed activation of smoke alarm system during a fire event on 17 October 2021.

<u>Issues</u> The report from FRNSW detailed a number of issues, in particular:

Issue	Council response	
Fire Safety Upgrade – A visual inspection of the	A review of Council records show the	
premises revealed that the installed essential fire	premises have been subject to two	
safety measures appear newer than the age of the	separate Fire Safety Orders. The last Fire	
building. It may be reasonable to assume that the	Safety Order was completed on 4 January	
	2000.	
Council previously required a fire safety upgrade.		
Annual Fire Safety Statement (AFSS) – Regulation	Inspection of the premises showed the	
89(4)(b) of the Environmental Planning and	Annual Fire Safety Statement was readily	
Assessment (Development Certification and Fire	accessible and was housed in an unlocked	
Safety) Regulation 2021 (EPAR 2021) requires the	cabinet adjacent to the entrance of the	
owner to display an AFSS within the building. The	premises, approximately 5 metres from the	
AFSS was displayed behind a locked glass display	FDCIE. This is in accordance with the	
cabinet. FRNSW prefers the statement to be	requirements of Clause 89(4)(b) of the	
located beside the Fire Brigade Panel (FBP) for	Environmental Planning and Assessment	
ease	(Development Certification and Fire	
	Safety) Regulation 2021.	
Fire Brigade Panel (FBP) / Alarm Signalling	The Council's recorded Fire Safety	
Equipment (ASE) – There were no faults or	Schedule for the premises lists the	
isolations to the FBP or ASE. However,	Automatic Detection and Alarm System's	
determining what Australian Standard applied was	Standard of Performance as BCA	
challenging as the AFSS is displayed behind a	Specification E2.2a Clause 4 AS 1670.	
locked glass cabinet		
Smoke Detection and Alarm System – As per the	The premises were subject to a previous	
AFSS placement, it was challenging to determine	Fire Order that required:	
what Australian Standard was used. The Council	Smoke alarms and detectors within	
may require a review to confirm that the following	residential apartments complying with	
observations are consistent with the approval:	AS 3786.	

Issue	Council response
A. The smoke detector type, location and spacings in the common areas varied throughout the premises.	Thermal detectors located within residential apartments within 5 metres of entrance doors complying with AS1670.
B. There are also red sounder bases intermittently spaced in different locations. It is unclear whether its use is specifically for building occupant warning or approved in its location.	 Smoke detectors complying with AS1670 to common and commercial areas of the premises. A Building Occupant Warning System in accordance with AS 1670.
	The Council has issued a Notice of Intention to Issue a Fire Safety Order (NOI) requiring works and certification of the: • Smoke detection and alarm systems; and
Maintenance – Regulation 81 of the Environmental	 Building Occupant Warning System. A. Inspection showed the service tags of
Planning and Assessment (Development Certification and Fire Safety) Regulation 2021	portable fire extinguishers and fire hose reels were last tagged in August 2023.
(EPAR 2021) requires maintenance of the	This is consistent with the requirements of
Essential Fire Safety Measure to a standard no less than when it was first installed. At the time of	AS1851 – 2012 Routine service of fire protection systems and equipment.
the inspection, authorised fire officers observed the	processor systems and equipment
following:	B. The Council has issued a NOI requiring:
A. The service tags for the portable fire	upgrading of an existing stairway to serve as an additional exit to the
extinguishers and fire hose reels were last tagged	residential apartments.
in March 2023	provision of suitable exit and directional exit signage.
B. The exit signs, paths, and doors may require review, as the Council may have approved the exit	
system in its current configuration. Items for Further Investigation – The Council may	2A. The Council has issued a NOI
require an investigation as the appropriate regulatory authority to confirm that:	requiring works and certification of the Building Occupant Warning System.
2A. The owners maintain the essential fire safety systems and meet the local Council's obligations to regulate the development consent approval. Specifically, whether the building occupant warning system is approved and sufficient to address the possible anomaly provided in the concern.	2.B The Council last received an Annual Fire Safety Statement for the premises endorsed by an accredited practitioner (fire safety) on 12 January 2023.
2B. An accredited practitioner (fire safety) has assessed, inspected and verified the performance of each fire safety measure (including exits) that applies to the building. Furthermore, the owner submits an Annual Fire Safety Statement (AFSS) as part of their obligations under the EP&A Act.	

FRNSW Recommendations

FRNSW have made no direct recommendation within their report other than legislative notification; however, FRNSW made comments as detailed in the above table.

COUNCIL INVESTIGATION OFFICER RECOMMENDATIONS:

Issue Order (NOI)	Issue emergency Order	Issue a compliance letter of instruction	Cited Matters rectified	Continue to undertake compliance action in response to issued Council correspondence	Continue with compliance actions under the current Council Order	Other (to specify)
-------------------------	-----------------------------	---	-------------------------------	--	--	--------------------------

As a result of a site inspection undertaken by Council investigation officers, a Notice of Intention (NOI) to issue an order has been served on the owner. Following the representation period of the NOI lapsing, it is recommended that Council exercise its powers for officers to serve a fire safety order under Schedule 5 of the Environmental Planning and Assessment Act, 1979 to address the fire safety deficiencies identified by FRNSW and the Council investigation officer.

The issue of a fire safety order will ensure that suitable fire safety systems are in position throughout the building to provide improved and adequate provisions for fire safety.

That the Commissioner of FRNSW be advised of Council's actions and determination.

Referenced/Attached Documents:

2023/541889	FRNSW s9.32 report dated 15 September 2023
2023/618647	Notice of Intention to Give an Order (NOI) dated 30 October 2023

OFFICIAL





File Ref. No: TRIM Ref. No: BFS21/3944 (17829)

D23/87181

Contact:

15 September 2023

General Manager City of Sydney GPO Box 1591 SYDNEY NSW 2001

Email: council@cityofsydney.nsw.gov.au

Attention: Manager Compliance/Fire Safety

Dear General Manager

Re: INSPECTION REPORT

'MIXED-USE RESIDENTIAL FLAT BUILDING'

11 WARD AVENUE POTTS POINT (hereafter the "the premises")

Fire & Rescue NSW (FRNSW) received correspondence on 19 October 2021 concerning the adequacy of the provision for fire safety in connection with 'the premises'.

The correspondence stated in part that:

Regarding fire attended at my neighbour 9/11 Ward Ave, Potts Point 2011 on 17/10/2021 - the smoke detectors had delayed activation. Although at home, I had no idea of a fire occurring as no smoke detector activated until "too late". No one knocked on my door to alert me, but I did hear other doors being banged on and this is what alerted me to a fire danger. I did not hear...

Pursuant to the provisions of Section 9.32(1) of the *Environmental Planning and Assessment Act 1979* (EP&A Act), Authorised Fire Officers from the Fire Safety Compliance Unit of Fire and Rescue NSW (FRNSW) inspected 'the premises' on 15 August 2023. On behalf of the Commissioner of FRNSW, the comments in this report are provided under Section 9.32(4).

The items listed in the comments of this report are based on the following limitations:

 A general overview of the building was obtained without using the development consent conditions or approved floor plans as a reference.

Fire and Rescue NSW	ABN 12 593 473 110	www.fire.nsw.gov.au
Community Safety Directorate	1 Amarina Ave	T (02) 9742 7434
Fire Safety Compliance Unit	Greenacre NSW 2190	F (02) 9742 7483

www.fire.nsw.gov.au

 Details of the Provisions for Fire Safety and Fire Fighting Equipment are limited to a visual inspection of the parts in the building accessed and the fire safety measures observed at the time.

COMMENTS

The following items were identified during the inspection:

- Investigation Outcomes The following items are provided to the Council as part of the investigation on Tuesday, 15 August 2023:
 - 1A. Fire Safety Upgrade A visual inspection of the premises revealed that the installed essential fire safety measures appear newer than the age of the building. It may be reasonable to assume that the Council previously required a fire safety upgrade.
 - 1B. Annual Fire Safety Statement (AFSS) Regulation 89(4)(b) of the Environmental Planning and Assessment (Development Certification and Fire Safety) Regulation 2021 (EPAR 2021) requires the owner to display an AFSS within the building. The AFSS was displayed behind a locked glass display cabinet. FRNSW prefers the statement to be located beside the Fire Brigade Panel (FBP) for ease.
 - 1C. Fire Brigade Panel (FBP) / Alarm Signalling Equipment (ASE) There were no faults or isolations to the FBP or ASE. However, determining what Australian Standard applied was challenging as the AFSS is displayed behind a locked glass cabinet.
 - 1D. Smoke Detection and Alarm System As per the AFSS placement, it was challenging to determine what Australian Standard was used. The Council may require a review to confirm that the following observations are consistent with the approval:
 - A. The smoke detector type, location and spacings in the common areas varied throughout the premises.
 - B. There are also red sounder bases intermittently spaced in different locations. It is unclear whether its use is specifically for building occupant warning or approved in its location.
 - 1E. Maintenance Regulation 81 of the Environmental Planning and Assessment (Development Certification and Fire Safety) Regulation 2021 (EPAR 2021) requires maintenance of the Essential Fire Safety Measure to a standard no less than when it was first installed. At the time of the inspection, authorised fire officers observed the following:
 - A. The service tags for the portable fire extinguishers and fire hose reels were last tagged in March 2023.

OFFICIAL

- B. The exit signs, paths, and doors may require review, as the Council may have approved the exit system in its current configuration.
- 2. Items for Further Investigation The Council may require an investigation as the appropriate regulatory authority to confirm that:
 - 2A. The owners maintain the essential fire safety systems and meet the local Council's obligations to regulate the development consent approval. Specifically, whether the building occupant warning system is approved and sufficient to address the possible anomaly provided in the concern.
 - 2B. An accredited practitioner (fire safety) has assessed, inspected and verified the performance of each fire safety measure (including exits) that applies to the building. Furthermore, the owner submits an Annual Fire Safety Statement (AFSS) as part of their obligations under the EP&A Act.

Please do not hesitate to contact of FRNSW's Fire Safety Compliance Unit at FireSafety@fire.nsw.gov.au or call if you have any questions or concerns regarding the above matters. Regarding this correspondence, please refer to file reference number BFS21/3944 (17829).

Yours faithfully

Fine Cofety Compliance Hei

Fire Safety Compliance Unit