

Attachment A

Fire Safety Reports Summary Sheet
--

Fire Safety Reports Summary Sheet

Total number of properties tabled: 12

Report – February 2026

Att.	Premises Specifics	Actions/ Recommendation
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	12 Ithaca Road, Elizabeth Bay	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
C	68-68A Darlinghurst Road, Potts Point	Premises inspected; matters raised have been rectified; no further action required.
D	44-44B Darlinghurst Road, Potts Point	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
E	2 Roslyn Street, Potts Point	Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
F	1 Martin Place, Sydney	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.

Att.	Premises Specifics	Actions/ Recommendation
G	60-70 Elizabeth Street, Sydney	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
H	78-80 George Street, Redfern	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
I	49-53 Regent Street, Chippendale	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
J	2-4 Cunningham Street, Haymarket	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
K	398-402 Sussex Street, Haymarket	Premises inspected; matters raised have been rectified; no further action required.
L	14-18 Lee Street, Haymarket	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
M	39 Dangar Place, Chippendale	Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.