

# **Attachment A**

**Fire Safety Report Summary Sheet**

**Fire Safety Report Summary Sheet  
 Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002**

Total number of properties tabled: 7

**Report- March 2019**

Summary table

Att. (A-H)	Premises Specifics ( <i>predominate building use</i> )	Actions/ Recommendation
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	13-15 Kellert Street, Potts Point, Licenced Premises	Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is required to be given to remedy identified fire safety deficiencies.
C	20-26 Bayswater Road, Potts Point, Licenced Premises (Candy's Nightspot)	Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
D	20-26 Bayswater Road, Potts Point, Licenced Premises (The World Bar [Carli Bar])	Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
E	19-35 Bayswater Road, Potts Point, Licenced Premises (Flamingo Lounge)	Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
F	19-35 Bayswater Road, Potts Point, Licenced Premises (The Club)	Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
G	60-60B Darlinghurst Road, Potts Point, Licenced Premises	Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
H	2-10 Darling Drive, Sydney, Retail Premises	Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.