

Attachment A

Fire Safety Report Summary Sheet

Fire Safety Report Summary Sheet
Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002

Total number of properties tabled: 3

Report – November 2021

Summary table

Att. (A-D)	Premises Specifics (<i>predominate building use</i>)	Actions/ Recommendation
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	94-96 Union Street, Pyrmont – The Pyrmont Bridge Hotel	Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is issued to address identified fire safety deficiencies.
C	229-231 Darlinghurst Road, Darlinghurst - The Kirkton Hotel	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
D	50-54 York Street, Sydney, AKA 1 Temperance Lane, Sydney – ‘Esteban Restaurant’	Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is issued to address identified fire safety deficiencies.