

# **Attachment A**

**Location Plan and Site Photographs**

# Glebe Street Playground

Glebe and Mitchell Streets, Glebe





Existing playground in the park, looking north from Glebe Street. Play equipment is at the end of its useful life and soft fall is worn and separating at edges. Playground is well shaded from the existing tree. Small area of turf in poor condition.



Looking east from Mitchell Street. Play equipment is at the end of its useful life and soft fall is worn and separating at edges. Planting areas are in reasonable condition. There is no paved access from Glebe Street. Low boundary walls are currently too low to be used comfortably as seating. There is one bench.