

ATTACHMENT A

**PHOTOGRAPHS OF RETAINING
STRUCTURE AND SITE MAP**

ATTACHMENT A

ATTACHMENT A – PHOTOGRAPHS OF RETAINING STRUCTURE



Photo 1 & 2 – Bulging and tilting sandstone block retaining wall. Steel brackets installed by Owners Corporation to support suspended access to building



