

ATTACHMENT A

**PHOTOGRAPHS OF WALL AND BEAMS
AND SITE MAP**

ATTACHMENT A

ATTACHMENT A – PHOTOGRAPHS OF WALL AND BEAMS

Photo 1 – Rusting beams supporting road and footway viewed from SCEGGS Darlinghurst




Photo 2 – Rusting beam supporting sandstone block wall that retains Thomson Street footway structure



ATTACHMENT A

