

ATTACHMENT A

**IMAGES OF ISSUES IMPACTING
TREES IN HYDE PARK**

Attachment A: Images of tree issues in Hyde Park



Images 1 and 2 – Port Jackson Fig that failed on 4 March 2013 (Hyde Park South) due to previous root damage.



Image 3 – Hills Fig (Tree 1N) that failed on 30 June (Hyde Park North) due to previous root damage and weather events.



Image 4 – Hills Fig that had an included branch failure in Hyde Park South (adjacent to War Memorial).



Image 5 – Hills Fig with an inclusion failure in Hyde Park North (adjacent to the Archibald Fountain)



Images 6 and 7 – Show the extent of decay at the base of a Hill's Fig tree following its removal in 2005.





Image 8 – The replacement Hills Figs trees being grown at the nursery. Note this photo was taken in 2012.

Plan showing location of the 16 trees to be removed




Large inclusion failure in 2005

11N (removed 1 July 13)

22N (removed 1 July 13)

1N (failed 30 June).

1S (removed 1 Aug 13)



Whole tree failure March 13

Large inclusion failure 2011

Hyde Park Tree Removals - Key

- decay
- significant inclusion
- root damage
- previous failure / removals

●
Images of the trees to be removed

Hyde Park North



Tree 124N Port Jackson Fig (College Street boundary).
Reason for removal - previous construction root damage, and the tree is in decline.



Tree 127N Plane Tree (College Street boundary)

Reason for removal - previous construction root damage; previous limb failure, and tree is declining in health.



Trees 185N Hill's Fig (central avenue - Archibald)
Reason for removal - due to decay.



Tree 206N Plane Tree (Elizabeth Street boundary)

Reason for removal - previous root damage and tree has poor form from being heavily suppressed.

Hyde Park South



Tree 14S Hill's Fig (central avenue)
Reason for removal - due to decay.



Tree 44S English Oak (NE section of HPS)

Reason for removal - previous construction root damage, and the tree is in decline.



Tree 81S, 83S - Hill's Fig (central avenue)
Reason for removal - due to decay.



Tree 131S Gingko (near Obelisk)
Reason for removal - the tree has started leaning, and its structural stability is compromised.




Tree 229S Port Jackson Fig (South East of ANZAC Memorial)
Reason for removal - previous construction root damage.



Tree 237S Port Jackson Fig (South East of ANZAC Memorial)
Reason for removal - previous construction root damage, and the tree is in decline.



Tree 251S Port Jackson Fig (South East of ANZAC Memorial)
Reason for removal - previous construction root damage, and the tree is in decline.



Tree 254S Port Jackson Fig (South East of ANZAC memorial)
Reason for removal - previous construction root damage.



Tree 292S Hill's Fig (south of Anzac War Memorial)
Reason for removal - Significant inclusion



Tree 345S Port Jackson Fig (west of Pool of reflection)
Reason for removal - previous construction root damage, and the tree is in decline. Note photo shows previous large root severed for pathway construction.



Tree 360S Brush Box (west of Pool of Reflection).
Reason for removal - previous construction root damage, and the tree is in decline.