

**ATTACHMENT C**

**PACKAGE 2 – POOL OF REFLECTION**



# ATTACHMENT C



**Image a)** Pool of Reflection – damaged tiles within the pool need to be replaced



**Image b)** Pool of Reflection- damaged tiles have been replaced creating a patchy visually effect.  
The grout between the tiles in many sections is missing.




**Image c)** Pool of Reflection- the surrounding coping is uneven and collapsing into the pool




**Image d)** Pool of Reflection- the surrounding coping is collapsing into the pool and gaps have been patched with concrete.

ATTACHMENT C

# ATTACHMENT C



Package 2  
Pool of Reflection Upgrade and War Memorial



**Legend**  
Pool of Reflection Upgrade and War Memorial

- Pavement upgrade
- New gravel pavement
- Upgrade / New garden bed
- Pool reconstruction
- Replacement kerb
- New 2-sided seat
- New pump room
- Replacement trees
- Existing trees