

ATTACHMENT D

**PACKAGE 3 – PATH RESTORATION AND
ENTRY ACCESS IMPROVEMENTS**



Image a) Poor accessibility - paths terminating at planting beds



Image b) Informal tracks through the grass created along pedestrian desire lines.

ATTACHMENT D



Image c) Inconsistent use of pavement materials



Image d) Broken sandstone edging and asphalt patched pavement



Image e) Broken pavers patched with coloured concrete



Image f) Broken pavers patched with asphalt

Legend


Pathway Restoration and Entry Access Improvements



Pathway Restoration and Entry Access Improvements



Upgrade / New garden bed



Package 3
Pathway Restoration and Entry Access Improvements