

ATTACHMENT E

**PACKAGE 4 – HYDE PARK CAFÉ
SURROUNDS**



Image a) Museum Café outdoor seating area lacking connection with adjacent parkland.



Image b) Museum Café – surrounding pavement areas damaged and uneven, creating accessibility issues

ATTACHMENT E



Scale
1:100 @ A1
1:200 @ A3



Package 4 (Preliminary)
Museum Station Cafe - Public Domain Upgrade

