

# ATTACHMENT C

## ATTACHMENT C

**BOWMAN STREET PHOTOS**



## ATTACHMENT C - BOWMAN STREET PHOTOS

Photo 1: Displacement of kerbs due to roots of existing juvenile trees.



Photo 2: Displacement of kerbs due to roots of existing juvenile trees.





Photo 3: lifted asphalt paving



Photo 4: lifted asphalt paving



Photo 5: lifted asphalt paving



Photo 6: lifted asphalt paving







Photo 7 & 8: Narrow offset from existing trees to building facade

