

Attachment A

Fire Safety Reports Summary Sheet
--

Fire Safety Reports Summary Sheet

Total number of properties tabled: 6

Report – May 2026

Att.	Premises Specifics	Actions/ Recommendation
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	782 Bourke Street, Waterloo	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
C	1 Taylor Street, Glebe	Premises inspected; owners issued with a Fire Safety Order to address identified fire-safety deficiencies; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
D	12 Primrose Avenue, Rosebery	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
E	25 Bligh Street, Sydney	Premises inspected; owners issued with corrective action correspondence. Follow up compliance site inspections found defective hydrant system; owners issued with a Fire Safety Order to address identified fire-safety deficiencies; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
F	37-43 Bay Street, Glebe	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.

Att.	Premises Specifics	Actions/ Recommendation
G	199 Cleveland Street, Redfern	Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.