

Attachment A

Location Plan and Site Photos



Alexandria Park, Alexandria




Existing toddler playground looking east towards Wyndham St. The playground equipment is at the end of its lifecycle with limited play offering. There is no seating within the fenced area for carers.



Existing Second playground looking west towards Park Rd. The playground equipment targeting older children is at the end of its lifecycle with limited play offering.



Looking east towards the picnic pergolas structures. The pergola structures are at the end of its lifecycle. Uneven and convoluted circulation pathways causing inefficient and confusing use of space.



Existing Tennis Amenity Block with adjacent tennis courts. Toilet amenities within the building very disconnected from the rest of the park. Tennis court surfaces uneven and not accessible to frequent users.