Attachment A

Fire Safety Report Summary Sheet

Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002 Fire Safety Report Summary Sheet

Total number of properties tabled: 13

Report-October 2018

Summary table

| Att. (A-N) | Premises Specifics (predominate building use) | Actions/ Recommendation |
|---------------|--|---|
| . ⋖ | Not applicable – Summary Sheet | Summary of clause 17, Schedule 5 matters tabled at Council meeting. |
| Å | √18-30A Martin-Place, Sydney; Premises ~~ under construction, part office building. | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| U | 122-122B Pitt Street, Sydney, Commercial Premises | Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| Ω | 200 Pitt Street, Waterloo, Residential Apartments | Premises are the subject of a current City fire safety order. This order is being compliance managed. Continued site inspections are being undertaken to ensure compliance with the terms of Councils order is achieved |
| Ш | 146-148 Glebe Point Road, Glebe, Backpackers Hostel | Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is required to be given to remedy identified fire safety deficiencies. |
| Щ | 1 Dixon Street, Sydney, Licensed Premises | Premises inspected, premises are subject to a current City Council fire order, follow up compliance activities are being undertaken to ensure required fire safety works are satisfactorily completed. |
| ပ | 614-628 George Street, Sydney, Licensed Premises | Premises inspected, premises are subject to a current City Council fire order, follow up compliance activities are being undertaken to ensure required fire safety works are satisfactorily completed. |
| I | 15 Goulburn Street, Haymarket, Licensed Premises | Premises are yet to be fully inspected, Fire and Rescue NSW report to be tabled and recommendation stood over to next meeting of Council to allow further detailed investigation to take place. |

| _ ¬ × J ∑ Z | 63-69 Dixon Street, Haymarket, Licensed Premises 31-37 Dixon Street, Haymarket, Licensed Premises 111 Fitzroy Street, Surry Hills, Boarding House 81-117 Broadway, Ultimo, Educational Facility 38 Macleay Street, Potts Point, Residential Apartments | Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is required to be given to remedy identified fire safety deficiencies. Premises inspected, premises are subject to a current City Council fire order, follow up compliance activities are being undertaken to ensure required fire safety works are satisfactorily completed. Premises are yet to be fully inspected, Fire and Rescue NSW report to be tabled and recommendation stood over to next meeting of Council to allow further detailed investigation to take place. Premises are yet to be fully inspected, Fire and Rescue NSW report to be tabled and recommendation stood over to next meeting of Council to allow further detailed investigation to take place. Premises inspected, owners to be issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
|-------------|--|--|
| Z | 229-249 Elizabeth Street, Sydney, Office Premises | Premises inspected, no significant fire safety issues identified; query on FRNSW building reference, report to be tabled only, Council officer to seek more information on the building location and reassess situation at the next meeting of Council. |