

Attachment A

**Round Three 2019/20 – Recommended for Funding
– Environmental Performance – Building
Operations Grant Program**

Environmental Performance Grants

Recommended for Funding

Environmental Performance – Building Operations Grant 2019-20 Round 3					
Organisation Name	Project Name	Project Description	\$ Amount Requested	\$ Amount Recommended	Conditions
Sscq (2000) Pty Ltd	Energy Management System - 93 Macquarie St, Sydney (Sir Stamford Hotel)	Installation of an energy management system in a 105 room hotel to monitor & reduce the use of gas and electricity.	\$10,000	\$10,000	Nil
Strata Plan 67022	Water and Electricity Monitoring - 11-21 Rose Street, Chippendale	Installation of an exhaust sensor & water monitoring system in a 5 level, 58 unit residential building to measure and improve energy and water use.	\$10,585	\$4,700	Nil
The Owners Of Strata Plan No 22014	Analysis of Condenser Water Plant - 2 Phillip Street, Sydney	Installation of a monitoring system in a 29 level, 48 unit residential building to determine if the water condenser plant can operate more efficiently.	\$9,000	\$9,000	Nil