

## **Attachment B**

**Photos of Required Completed Works**



Fig. 1 – Reconstructed steel entrance gates Ground Floor southern end




Fig. 2 - Reconstructed steel entrance gates Ground Floor southern end



Fig. 3 - Reconstructed steel entrance gates Ground Floor George Street entry




Fig. 4 - Reconstructed steel entrance gates Ground Floor, York Street entry



Fig. 5 – New escalators southern end First Floor




Fig. 6 - New escalators southern end First Floor



Fig. 7 – Steel suspension structure for new escalators southern end Second Floor




Fig. 8 - New escalators northern end Second Floor





Fig. 9 - New escalators southern end First Floor



Fig. 10 – New BCA compliant glass and metal balustrade




Fig. 11 - New BCA compliant glass and metal balustrade



Fig. 12 - New BCA compliant glass and metal balustrade





Fig. 13 – Contemporary shopfronts, Ground Floor



Fig. 13 – Contemporary shopfronts, Ground Floor



Fig. 13 – Contemporary shopfronts, Second Floor



Fig. 13 – Contemporary shopfronts, Ground Floor



Fig. 14 – New illuminated signage Second Floor



Fig. 15 - New custom designed carpet Second Floor



Fig. 16 - New colour scheme southern gallery, First Floor



Fig. 17 - New colour scheme northern gallery, Second Floor




Fig. 18b - New colour scheme central core