

# **Attachment A**

<b>Fire Safety Report Summary Sheet</b>
---

**Fire Safety Report Summary Sheet**  
**Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002**

**Total number of properties tabled: 7**

**Report- May 2020**

**Summary table**

<b>Att. (A-D)</b>	<b>Premises Specifics (<i>predominate building use</i>)</b>	<b>Actions/ Recommendation</b>
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	13-19 Glebe Street, Glebe Residential Apartments	Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is required to be given to remedy identified fire safety deficiencies.
C	165 Pitt Street, Sydney Accommodation Hotel	Premises inspected, no significant fire safety issues identified; fire safety certification current and compliant. Report to be noted. No further action required.
D	123-129 Clarence Street, Sydney Ground floor Restaurant and upper floors Commercial Offices	Premises inspected, owners have been served with corrective action correspondence; follow up compliance site inspections confirmed fire safety works are satisfactorily completed. No further action.
E	55 Pirrama Road, Pyrmont The Star Casino	Premises inspected, no significant fire safety issues identified; fire safety certification current and compliant. Report to be noted. No further action required.
F	12 Darling Drive, Sydney Accommodation Hotel	Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is required to be given to remedy identified fire safety deficiencies.
G	61-63 Market Street, Sydney Commercial Offices	Premises inspected, Council officer has determined that a notice of intention to issue a fire safety order is required to be given to remedy identified fire safety deficiencies.
H	122-124 Flinders Street, Darlinghurst Hotel and Bar	Premises inspected, owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.