

Attachment A

**Recommended 2020/21 Environmental Performance –
Building Operations Grant Program – Round One**

Environmental Performance Grants

Recommended for Funding

Environmental Performance – Building Operations Grants 2020-21 Round 1					
Organisation Name	Project Name	Project Description	\$ Amount Requested	\$ Amount Recommended	Conditions
Dexus Funds Management Limited	Waste Measuring System - 19 Martin Place, Sydney (MLC Tower)	Installation and supply of a waste measuring system in a 61,651 net lettable area tenancy to provide automated reporting to assist building managers and tenants to achieve better recycling outcomes.	\$10,000	\$10,000	Applicant to provide a case study for public distribution together with a report on their outcomes
Glory Property III Investment Pty. Ltd.	Energy Sub-Meter Installation - 488 George St Sydney (Hilton Hotel)	Installation and supply of an energy sub-meter system in a 587 room hotel across key facility points to provide specific data and trends on key areas of the hotel's facilities.	\$10,000	\$10,000	Applicant to provide an estimate of the expected energy reduction of this energy sub-metering and to update their analysis following the implementation of the sub metering for their acquittal.