

Attachment A

Location Plan and Site Photos

Wattle Lane Playground / McKee Street Reserve

McKee Street, Ultimo





Existing playground in the reserve – play equipment is at the end of its lifecycle; soft-fall is worn and separating from edges. Playground is well shaded from the existing trees and shade structure.



Looking north along McKee Street. Uneven paving along the footpath due to tree roots.



Small area of turf at northern end in poor condition.



Existing stairs from Wattle Lane (to be retained). Movement and cracking of brick retaining wall.



Garden beds are well-managed and utilised by local community garden group.