

Attachment A

Fire Safety Report Summary Sheet

Fire Safety Report Summary Sheet
Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002

Total number of properties tabled: 12

Report – September 2023

Summary table

Att. (A-D)	Premises Specifics	Actions/ Recommendation
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	429-429A Pitt Street, Haymarket	Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
C	7 Potter Street, Waterloo	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
D	115-119 Macquarie Street, Sydney	Premises inspected; matters raised have been rectified, no further action required.
E	32-38 Rothschild Avenue, Rosebery	Premises inspected; works to continue under an existing Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
F	87-93 Abercrombie Street, Chippendale	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
G	695-699 George Street, Haymarket	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
H	2 Roslyn Street, Potts Point	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
I	30-34 Chalmers Street, Surry Hills	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.

J	75 Crown Street, Woolloomooloo	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
K	1-21 Bay Street, Glebe	Premises inspected; matters raised have been rectified, no further action required.
L	38 Chalmers Street, Surry Hills	Premises inspected; matters raised have been rectified, no further action required.
M	281-285 Broadway, Glebe	Premises inspected; works to continue under an existing Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.