

Attachment A

| |
|---|
| Fire Safety Report Summary Sheet |
|---|

Fire Safety Report Summary Sheet
Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002

Total number of properties tabled: 10

Report – February 2024

Summary table

| Att. (A-K) | Premises Specifics | Actions/ Recommendation |
|---------------|-------------------------------------|--|
| A | Not applicable – Summary Sheet | Summary of clause 17, Schedule 5 matters tabled at Council meeting. |
| B | 288-310 Wattle Street, Ultimo | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| C | 63-65 Flinders Street, Surry Hills | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| D | 9 Ward Avenue, Potts Point | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| E | 133-145 Castlereagh Street, Sydney | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| F | 163-169 Oxford Street, Darlinghurst | Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| G | 6 Central Park Avenue, Chippendale | Premises inspected; matters raised have been rectified, no further action required. |
| H | 25 Geddes Street, Zetland | Premises inspected; matters raised have been rectified, no further action required. |
| I | 354-358 Bourke Street, Surry Hills | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| J | 11 Charles Street, Erskineville | Premises inspected; owners have been issued with a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |

| Att. (A-K) | Premises Specifics | Actions/ Recommendation |
|---------------|---------------------------------|---|
| K | 85-91 Oxford Street, Darlington | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |