

# **Attachment A**

**Location Plan and Site Photographs**

# Ada Villa Terrace (59 Erskineville Road)

## Erskineville Road, Erskineville





Existing reserve looking south towards the rear of the site– the paving is at the end of its lifecycle. The site is exposed from the recently removed neighbouring trees. Small planting area in poor condition.



Looking south towards Erskineville Road. Uneven paving and fencing cause by the trees from the neighbouring property which are now removed.