

Attachment A

Fire Safety Report Summary Sheet

Fire Safety Report Summary Sheet
Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002

Total number of properties tabled: 7

Report – June 2024

Summary table

Att. (A-H)	Premises Specifics	Actions/ Recommendation
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	359-361 Pitt Street, Sydney	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
C	156-160 Goulburn Street, Surry Hills	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
D	405-411 Sussex Street, Haymarket	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
E	301 Kent Street, Sydney	Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
F	782 Bourke Road, Waterloo	Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
G	252 Botany Road Alexandria	Premises inspected; owners have previously been issued with a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
H	33-35A York Street, Sydney	Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.