## **Attachment A**

**Fire Safety Reports Summary Sheet** 

## Fire Safety Reports Summary Sheet

Total number of properties tabled: 5

Report – September 2025

| Att. | Premises Specifics                        | Actions/ Recommendation  |
|------|---|--|
| Α    | Not applicable – Summary Sheet            | Summary of clause 17, Schedule 5 matters tabled at Council meeting.  |
| В    | 47-61 Pyrmont Bridge Road,<br>Camperdown  | Premises inspected; owners have previously been issued with a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.                    |
| С    | 120-122 Saunders Street,<br>Pyrmont       | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.                  |
| D    | 107-109 Darlinghurst Road,<br>Potts Point | Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.                  |
| E    | 9-15 Macarthur Street, Ultimo             | Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |
| F    | 180 Pitt Street, Waterloo                 | Premises inspected; owners have been issued with a Notice of Intention to give a Fire Safety Order; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed. |